

Sheet G1		
Item/Topic	City of Sammamish Comments	King County Responses
1	The District's contact name should be revised to Kyle Wong and the phone extension number to #203.	Not a shoreline comment: This comment is not relevant to the City's review of the shoreline substantial development permit application as it addresses matters outside the scope of the Shoreline Management Act and the City of Sammamish Shoreline Master Program. The County will separately respond to such comments received as part of the SSDP review process that are outside the scope of this permit application in the summer or fall of 2017.
Sheet SP2		
2	Potential conflict west of Station 473+00 with existing 3" HDPE SSFM with regards to the removal of the existing gravel surface and installation of the silt fence.	Not a shoreline comment: This comment is not relevant to the City's review of the shoreline substantial development permit application as it addresses matters outside the scope of the Shoreline Management Act and the City of Sammamish Shoreline Master Program. The County will separately respond to such comments received as part of the SSDP review process that are outside the scope of this permit application in the summer or fall of 2017.
Sheet AL2		
3	Potential conflict west of Station 473+00 with the existing 3" HDPE SSFM and grinder pump service lines to Tax Parcel #3575300230 and #3575300245 with regards to the installation of the rock wall.	Not a shoreline comment: This comment is not relevant to the City's review of the shoreline substantial development permit application as it addresses matters outside the scope of the Shoreline Management Act and the City of Sammamish Shoreline Master Program. The County will separately respond to such comments received as part of the SSDP review process that are outside the scope of this permit application in the summer or fall of 2017.
Sheet UP 1		
4	A backflow prevention device, either a Double Check Valve Assembly (DCVA) or a Reduced Pressure Backflow Assembly (RPBA), will be required to be installed directly behind the water meter at Station 102+02.2. The type of device required will be dependent on the proposed restroom design and fixtures.	Not a shoreline comment: This comment is not relevant to the City's review of the shoreline substantial development permit application as it addresses matters outside the scope of the Shoreline Management Act and the City of Sammamish Shoreline Master Program. The County will separately respond to such comments received as part of the SSDP review process that are outside the scope of this permit application in the summer or fall of 2017.
5	The proposed steel casing for the 1.25-inch sewer forcemain should be revised to be 10-foot in length, being centered along the wall crossing point. In addition, a detail regarding the proposed seal at the end of the casing and casing spacers should be added to the drawings.	Not a shoreline comment: This comment is not relevant to the City's review of the shoreline substantial development permit application as it addresses matters outside the scope of the Shoreline Management Act and the City of Sammamish Shoreline Master Program. The County will separately respond to such comments received as part of the SSDP review process that are outside the scope of this permit application in the summer or fall of 2017.
Sheet PS1		
6	A potential conflict may arise with the proposed 1.25-inch sewer forcemain to the proposed restroom and the proposed landscaping. District standards do not allow trees or bushes above the grinder service line due to operation and maintenance issues.	Not a shoreline comment: This comment is not relevant to the City's review of the shoreline substantial development permit application as it addresses matters outside the scope of the Shoreline Management Act and the City of Sammamish Shoreline Master Program. The County will separately respond to such comments received as part of the SSDP review process that are outside the scope of this permit application in the summer or fall of 2017.
Sheet PS2		
7	Potential conflict west of Station 473+00 with the existing 3" HDPE SSFM and grinder pump service lines to Tax Parcel #3575300230 and #3575300245 with regards to the installation of the rock wall.	Not a shoreline comment: This comment is not relevant to the City's review of the shoreline substantial development permit application as it addresses matters outside the scope of the Shoreline Management Act and the City of Sammamish Shoreline Master Program. The County will separately respond to such comments received as part of the SSDP review process that are outside the scope of this permit application in the summer or fall of 2017.